



XX = AA, GN, ...

10	A 860 901 XX
11	A 861 448 XX
12	A 6680 AA
13	A 6677 XX

A 7385 ..	
Pos.	Part No.
1	A 963 523 NU
3	A 960 500 NU
4	A 861 000 NU
5	A 963 526 NU
7	A 861 441 XX
8	A 860 899 NU
9	A 861 447 XX
11	A 861 448 XX
12	A 6679 AA
13	A 6677 XX



www.idealstandardinternational.com



Ideal Standard

Joy

A 7385 .. A 7386 ..

1019 / A 868 626

