





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA,AD

- 1 A 963 313 XX
- 2 A 963 054 NU
- 3 A 963 309 NU
- 4 B 960 862 XX
- 6 A 963 314 NU
- 7 A 963 785 NU
- 10 A 963 788 NU
- 11 A 963 324 NU
- 14 A 961 118 NU
- 16 A 960 019 XX
- 17 A 963 369 XX
- 19 A 960 949 NU
- 20 A 963 357 XX
- 21 A 963 404 NU
- 22 A 961 230 XX




## CERAMIX BLUE


A 5655 .. A 5657 ..

0211 / A 866 393  
 (+ A 865 612)  
 Made in Germany

	<b>P</b>	bar				<b>Q</b> (3 bar)
	<b>T</b>	°C				<b>l/min</b> 5




A 5655 ..








A 5657 ..



Ideal Standard  
 Roentgenstrasse 9  
 54516 Wittlich  
 Germany





P	T	°C	1	2	3	4	5	6	7	8
			°C	°C	°C	°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	15°C	47,4	47	44,5	39,9	35,7	33,9	30,7	29,6
	65°C	15°C	61,3	60,7	57,2	50,6	44,6	41,9	37,4	35,9
	85°C	15°C	79,8	79	74	64,8	56,4	52,7	46,3	44,3